



1
Fix the tripod at the hole on the bottom of the mount



2
Disjoint the camera shoe from the mount



3
Attach the shoe to the camera



4
Insert and tighten the camera in the mount block



5
Attach the external battery to the tripod



6
Connect the LANC cables and power cable to the mount control



7
Supply power to the mount by pushing the power button at the battery



8
Adjust distance and angles of the two cameras



9
If the balance is not right, adjust the height of the shoe